

Message

From: Nonresponsive based on revised scope
Sent: 8/26/2020 4:04:20 PM
To: Wagner, Christine [Wagner.Christine@epa.gov]
Subject: Fwd: Measurements of the Excavation Areas for Shiloh Church Road Project
Attachments: image002.jpg; image003.jpg; ShilohProperty3map.pdf

Nonresponsive based on revised scope

From: Nonresponsive based on revised scope
Sent: Wednesday, August 26, 2020, 12:01 PM
To: Nonresponsive based on revised scope
Subject: RE: Measurements of the Excavation Areas for Shiloh Church Road Project

Nonresponsive based on revised scope

I attached my map of property 3 to this e-mail. The first page is START's sampling map. The next 2 pages are my horrible sketchings based on the areas Chris walked us to and using the sample points on page 1 as a reference. On the last section near sample P3-6, we will need to dig up the whole 349 ft of pathway. I didn't shade the whole thing, but it all has battery chips. Chris only wants to do a scraping to remove the bulk of visible contamination on the top surface. I would say a 6 inch scrape all over. That was back in April though. She might have something different in mind now. Thanks.

Nonresponsive based on revised scope

Nonresponsive based on revised scope

From: Nonresponsive based on revised scope
Sent: Wednesday, August 26, 2020 11:38 AM
To: Nonresponsive based on revised scope
Subject: Measurements of the Excavation Areas for Shiloh Church Road Project
Importance: High

, hope all is well. The OSC says you have the measurements of property 1 at the subject site. She says you two measured them together and you recorded the measurements. Can you please send those to me?

Nonresponsive based on revised scope

[20 Years Logo_Web]

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the

ED_013731A_00000884-00001

sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.